

Fishing Job for Screen Recovery

Wellsite's Permian operations team was called on to assist an operator with the recovery of a downhole screen used for sand control. The screen had come apart during a production tubing retrieval operation, when the screen slid off the main assembly body, causing an obstruction in the well.

After several attempts to retrieve the screen, the operator decided to contact Wellsite's expert fishing team. Our supervisor arrived on location with a preliminary retrieval plan in hand. After reviewing with the company man and workover rig supervisor, our team adjusted the plan for current conditions, briefed the team on location and went to work. Wellsite's team quickly retrieved the screen with the applicable tool. The operator was pleased with the minimal retrieval time required, as well as the execution provided by the Wellsite fishing team.



Screen recovered downhole